



Pos.	Description
1	Porcelain
2	Copper rod
3	Brass cap "E"
4	Brass top washer "F"
7	NBR ring gasket "J"
8	Gasket "O"
9	NBR gasket "M"
10	NBR Flange gasket "N"
11	Brass Flag
12	Brass ring "P"
13	Copper ring "S"
14	Brass nut M75 DIN 934
16	Fiber gasket
17	Vent/screw "R"
18	Locking screw
24	S/S fixing ring
25	Aluminium clamping piece "F"
26	Nuts M12 DIN934
27	Washer ϕ 13
28	Fixing stud M12x70 (not supplied)
33+35	Equipotential link

Bushing	Voltage kV	Current A	Creepage distance mm	PF 1' kV	BIL kV	Z n° of sheds
20/6300	24	6300	440	55	125	3